

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 01/06/25 12:43 Project: Secaucus HQ Date Received: 01/06/25 Client Sample ID: SDG No.: Q1018 3730 Lab Sample ID: Q1018-05 Matrix: Water % Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Flash Point	>212		1	0	0	o F		01/07/25 11:10	1010B
pН	7.70	Н	1	0	0	pН		01/07/25 08:50	9040C
Reactive Cyanide	0.0050	U	1	0.00099	0.0050	mg/L	01/10/25 08:30	01/10/25 10:42	9012B
Reactive Sulfide	1.00	U	1	0.43	1.00	mg/L	01/08/25 15:30	01/09/25 09:24	9034

Other method reference for flash point: Pensky-Martens Closed Cup Flash Point ASTM D 93 - IP 34, pH result reported at temperature

U = Not Detected

Comments:

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits