

Report of Analysis

Client:	GFE LLC	Date Collected:	
Project:	182 Ralph Ave, Brooklyn NY	Date Received:	
Client Sample ID:	VL0107ABS01	SDG No.:	Q1031
Lab Sample ID:	VL0107ABS01	Matrix:	Air
Analytical Method:	TO-15	Test:	VOCMS Group3
Sample Wt/Vol:	400	Units:	mL

File ID/Qc Batch:	Dilution:	Prep Date	Date Analyzed	Prep Batch ID
VL041854.D	1		01/07/25 20:36	VL010725

CAS Number	Parameter	Conc. ppbv	Conc. ug/M3	Qualifier	MDL	LOQ / CRQL	Units
TARGETS							
75-01-4	Vinyl Chloride	9.20	23.5		0.030	0.080	ug/m3
75-35-4	1,1-Dichloroethene	9.80	38.9		0.56	1.98	ug/m3
156-59-2	cis-1,2-Dichloroethene	10.3	40.8		0.36	1.98	ug/m3
71-55-6	1,1,1-Trichloroethane	10.2	55.6		0.050	0.16	ug/m3
79-01-6	Trichloroethene	10.7	57.5		0.11	0.16	ug/m3
127-18-4	Tetrachloroethene	11.6	78.7		0.14	0.20	ug/m3
SURROGATES							
460-00-4	1-Bromo-4-Fluorobenzene	10.7			65 - 135	107%	SPK: 10
INTERNAL STANDARDS							
74-97-5	Bromochloromethane	86000		2.793			
540-36-3	1,4-Difluorobenzene	195000		3.971			
3114-55-4	Chlorobenzene-d5	166000		8.894			

U = Not Detected

RL = Reporting Limit

MDL = Method Detection Limit

E = Value Exceeds Calibration Range

D = Dilution

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

Q = indicates LCS control criteria did not meet requirements