

Report of Analysis

Client:	Dewberry Engineers Inc.			Date Collected:		01/09/25 11:00	
Project:	PennDOT - Onvo Travel Plaza #50040379			ate Received:	01/09/25	i	
Client Sample ID:	MW-1DL			SDG No.:		Q1061	
Lab Sample ID:	Q1061-01DL	Ν	Matrix:		WATER		
			%	6 Solid:	0		
Parameter	Conc. Qua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Chloride	27.7 D 10 0.11	6.00	mg/L		01/10/25 15:3	35 300.0	

Comments:

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

- J = Estimated Value
- B = Analyte Found in Associated Method Blank
- * = indicates the duplicate analysis is not within control limits.
- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits