

Report of Analysis

Client:	Dewberry Engineers Inc.	Date Collected:	01/09/25 11:41
Project:	PennDOT - Onvo Travel Plaza #50040379	Date Received:	01/09/25
Client Sample ID:	MW-3DL	SDG No.:	Q1061
Lab Sample ID:	Q1061-03DL	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	122	D	50	0.55	30.0	mg/L		01/10/25 16:18	300.0

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits