

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Dewberry Engineers Inc. Date Collected: 01/09/25 12:02

Project: PennDOT - Onvo Travel Plaza #50040379 Date Received: 01/09/25

Client Sample ID: MW-4DL SDG No.: Q1061

Lab Sample ID: Q1061-04DL Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	114	D	50 0.55	30.0	mg/L		01/10/25 16:39	300.0

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits