

## **Report of Analysis**

Client:	Dewberry Engineers Inc.			octed: 01/09/25 13:14	
Project:	PennDOT - Onvo Travel Plaza #50040379		Date Rece	ived: 01/09/25	
Client Sample ID:	MW-8DL2	SDG No.:	Q1061		
Lab Sample ID:	Q1061-08DL2		Matrix:	WATER	
			% Solid:	0	
Parameter	Conc. Qua. DF MDL	LOQ / CRQL	Units Prep	Date Date Ana. An	a Met.
Chloride	103 D 50 0.55	30.0	mg/L	01/10/25 19:53 30	0.0

Comments:

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

- J = Estimated Value
- B = Analyte Found in Associated Method Blank
- \* = indicates the duplicate analysis is not within control limits.
- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits