

Report of Analysis

Client:	Dewberry Engineers Inc.	Date Collected:	01/09/25 14:20
Project:	PennDOT - Onvo Travel Plaza #50040379	Date Received:	01/09/25
Client Sample ID:	MW-10DL	SDG No.:	Q1061
Lab Sample ID:	Q1061-10DL	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	186	OR	5	0.055	3.00	mg/L		01/10/25 20:57	300.0
Nitrate	25.5	D	5	0.017	2.50	mg/L		01/10/25 20:57	300.0
Sulfate	51.0	D	5	0.16	15.0	mg/L		01/10/25 20:57	300.0
Phosphorus, Total	2.56	D	5	0.024	0.25	mg/L	01/15/25 11:45	01/15/25 14:15	365.3

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits