

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Dewberry Engineers Inc. Date Collected: 01/09/25 14:20 Project: PennDOT - Onvo Travel Plaza #50040379 Date Received: 01/09/25 Client Sample ID: MW-10DL2 SDG No.: Q1061 Lab Sample ID: Q1061-10DL2 Matrix: WATER

% Solid: 0

| Parameter | Conc. | Qua. | DF MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|-------|------|---------|------------|-------|-----------|----------------|----------|
| Chloride | 167 | D | 50 0.55 | 30.0 | mg/L | | 01/10/25 22:02 | 2 300.0 |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits