

Report of Analysis

Client:	Dewberry Engineers Inc.	Date Collected:	01/09/25
Project:	PennDOT - Onvo Travel Plaza #50040379	Date Received:	01/09/25
Client Sample ID:	MW-3	SDG No.:	Q1061
Lab Sample ID:	Q1061-03	Matrix:	Water
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-09-7	Potassium	21900	1	281		1000	ug/L	01/13/25 10:30	01/20/25 15:58	EPA 200.7	
7440-23-5	Sodium	88500	1	448		1000	ug/L	01/13/25 10:30	01/20/25 15:58	EPA 200.7	

Color Before:	Brown	Clarity Before:	Clear	Texture:
Color After:	Colorless	Clarity After:	Clear	Artifacts:
Comments:	Metals Group1			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N =Spiked sample recovery not within control limits