

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Dewberry Engineers Inc. Date Collected: 01/09/25 Project: PennDOT - Onvo Travel Plaza #50040379 Date Received: 01/09/25 Client Sample ID: MW-7 SDG No.: Q1061 Lab Sample ID: Q1061-07 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua. DF M	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-09-7	Potassium	12000	1 2	81	1000	ug/L	01/13/25 10:30	01/20/25 16:16	EPA 200.7	,
7440-23-5	Sodium	64700	1 4	48	1000	ug/L	01/13/25 10:30	01/20/25 16:16	EPA 200.7	•

Color Before: Brown Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group1

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits