

Duplicate Sample Summary

Client: Tully Environmental, Inc	SDG No.: Q1083
Project: Transfer Station-SPDES	Sample ID: Q1083-01
Client ID: 001-WILLETS-PT-BLVD(DEC)DUP	Percent Solids for Spike Sample: 0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
TSS	mg/L	+/-5	33.8		34.0		1	0.59		01/16/2025