

Report of Analysis

| | | | |
|-------------------|-----------------|-----------------|----------------|
| Client: | PSEG | Date Collected: | 01/15/25 10:38 |
| Project: | Roseland Switch | Date Received: | 01/15/25 |
| Client Sample ID: | RT-3407 | SDG No.: | Q1093 |
| Lab Sample ID: | Q1093-01 | Matrix: | SOIL |
| | | % Solid: | 93.7 |

| Parameter | Conc. | Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|--------------|-------|------|----|------|------------|----------|-----------|----------------|----------|
| Paint Filter | 1.00 | U | 1 | 1.00 | 1.00 | ml/100gm | | 01/17/25 11:45 | 9095B |

Comments: _____

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements
 H = Sample Analysis Out Of Hold Time

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N =Spiked sample recovery not within control limits