

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Weston Solutions Date Collected: 01/15/25 12:20

Project: Ft Meade Tipton Airfield Parcel RI - PO 0111169 Date Received: 01/16/25

Client Sample ID: TAPIAL1-MW04I-011525-00-T3 SDG No.: Q1109

Lab Sample ID: Q1109-01 Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TOC	0.98	J	1	0.19	0.50	1.00	mg/L		01/17/25 10:39	9060A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits