



Report of Analysis

Client: Weston Solutions Date Collected:

Project: Ft Meade Tipton Airfield Parcel RI - PO 0111169 Date Received:

Client Sample ID: VBF0117W1 SDG No.: Q1109
Lab Sample ID: VBF0117W1 Matrix: Water

Analytical Method: 8015D GRO % Solid: 0 Decanted:

Sample Wt/Vol: 5 Units: mL Final Vol: 5 mL

Soil Aliquot Vol: uL Test: Gasoline Range Organics

Extraction Type: Injection Volume:

GPC Factor: PH:

Prep Method:

File ID/Qc Batch: Dilution: Date Analyzed Prep Batch ID

FB031314.D 1 01/17/25 9:35 FB011725

CAS Number	Parameter	Conc.	Qualifier	MDL	LOD LOQ	/ CRQL	Units
TARGETS GRO	GRO	9.00	U	6.00	9.00	45.0	ug/L
SURROGATES 98-08-8	Alpha,Alpha,Alpha-Trifluoro	to 18.5		50 - 150		92%	SPK: 20

Comments:

U = Not Detected

LOO = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit