

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Major Products Date Collected: 01/16/25 11:30 Project: Floor Drain Water 2025 Date Received: 01/16/25 Client Sample ID: DRAIN WATER TANK-1 SDG No.: Q1111 Lab Sample ID: Q1111-01 Matrix: WATER % Solid: 0

Parameter	Conc. Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
BOD5	5190	1	0.17	2.00	mg/L		01/16/25 16:50	SM 5210 B-16
TSS	290	1	1.00	4.00	mg/L		01/17/25 09:45	SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits