

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Parkway Generation Operating LLC Date Collected: 01/16/25 Project: Linden Generating Station - LRSA Date Received: 01/16/25 Client Sample ID: **DSN002** SDG No.: Q1113 Lab Sample ID: Q1113-01 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-47-3	Chromium	2.96	J	1	0.52	5.00	ug/L	01/17/25 08:55	01/20/25 14:51	EPA 200.7	
7440-66-6	Zinc	179		1	1.44	20.0	ug/L	01/17/25 08:55	01/20/25 14:51	EPA 200.7	

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group3

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits