

Duplicate Sample Summary

Client: Tully Environmental, Inc	SDG No.: Q1145
Project: Transfer Station-SPDES	Sample ID: Q1140-01
Client ID: FRAC-TANK-F06078DUP	Percent Solids for Spike Sample: 0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
TSS	mg/L	+/-5	68.2		68.3		1	0.15		01/22/2025