

Lab Sample ID:

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Matrix:

Water

Fax: 908 789 8922

Q1157-01

Report of Analysis

Client: CHA Companies, Inc. Date Collected: 01/22/25 10:20

Project: 355320 Kingsboro PC Bldgs. 2 & 28 Interior Reno Date Received: 01/22/25

Client Sample ID: B2-W10-RM2016-SINK SDG No.: Q1157

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Residual Chlorine	0.086	HJ	1	0.016	0.10	mg/L		01/23/25 09:36	SM 4500-Cl G-11
Turbidity	0.77	J	1	0.075	1.00	NTU		01/23/25 14:44	SM 2130 B-11

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits