

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Report of Analysis**

Client: CHA Companies, Inc. Date Collected: 01/22/25 10:00

Project: 355320 Kingsboro PC Bldgs. 2 & 28 Interior Reno Date Received: 01/22/25

Client Sample ID: B2-W10-RM2019-EYEWASH SDG No.: Q1157

Lab Sample ID: Q1157-05 Matrix: Water

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Residual Chlorine	0.11	Н	1	0.016	0.10	mg/L		01/23/25 09:57	SM 4500-Cl G-11
Turbidity	0.71	J	1	0.075	1.00	NTU		01/23/25 15:04	SM 2130 B-11

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits