

 $284 \; Sheffield \; Street, \; Mountainside, \; New \; Jersey \; 07092, \; Phone \; : \; 908 \; 789 \; 8900, \\$

Fax: 908 789 8922

Report of Analysis

Client: Chemtech Consulting Group Date Collected: 01/13/25 10:00 Project: NJ Drinking Water PT Date Received: 01/15/25 Client Sample ID: PT-TURB-WS SDG No.: Q1172 Lab Sample ID: Q1172-02 Matrix: Water % Solid:

Parameter	Conc. Qu	ua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Turbidity	7.12	1 0.075	1.00	NTU		02/13/25 11:0	08 SM 2130 B-11

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits