

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Chemtech Consulting Group Date Collected: 01/13/25 Project: NJ Drinking Water PT Date Received: 01/15/25 Client Sample ID: PT-SIO2-WS SDG No.: Q1172 Lab Sample ID: Q1172-06 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met. Prep Met.
Dissolved	Dissolved	10900	1 128	856	ug/L	02/12/25 10:00	02/18/25 14:10	EPA 200.7
Silica	Silica							

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Silica

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits