

Report of Analysis

Client:	Weston Solutions	Date Collected:	01/24/25 13:45
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169	Date Received:	01/25/25
Client Sample ID:	TAPIAL3-MW04S-012425-00-T3	SDG No.:	Q1193
Lab Sample ID:	Q1193-01	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TOC	10.0		1	0.19	0.50	1.00	mg/L		01/28/25 13:24	9060A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits