

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Weston Solutions Date Collected: 01/24/25 15:40 Project: Ft Meade Tipton Airfield Parcel RI - PO 0111169 Date Received: 01/25/25 Client Sample ID: TAPIAL2-MW01-012425-00-T2 SDG No.: Q1193 Lab Sample ID: Q1193-02 Matrix: WATER

% Solid:

| Parameter | Conc. Qua. | DF MDL | LOD | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|------------|--------|------|------------|-------|-----------|----------------|----------|
| TOC | 2.40 | 1 0.19 | 0.50 | 1.00 | mg/L | | 01/28/25 14:14 | 9060A |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits