

 $284 \; Sheffield \; Street, \; Mountainside, \; New \; Jersey \; 07092, \; Phone \; : \; 908 \; 789 \; 8900, \\$

Fax: 908 789 8922

Report of Analysis

Client: Weston Solutions Date Collected: 01/27/25 14:52 Project: Ft Meade Tipton Airfield Parcel RI - PO 0111169 Date Received: 01/28/25 Client Sample ID: TAPHHA-MW12-012725-00-T2 SDG No.: Q1201 Lab Sample ID: Q1201-01 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua.	DF MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TOC	4.20	1 0.19	0.50	1.00	mg/L		01/28/25 15:43	9060A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits