

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Date Received:

Matrix:

Final Vol:

01/28/25

5

Decanted:

mL

Fax: 908 789 8922

Report of Analysis

Client: RU2 Engineering, LLC

Date Collected: 01/27/25

Project: NYCDDC SANTWOBR Brooklyn Bridge BBMCR

> JPP-20.1-012725 SDG No.: Q1206

Client Sample ID:

Lab Sample ID: Q1206-01 **SOIL** 8015D GRO % Solid: 85.5 Analytical Method:

Sample Wt/Vol: 4.99 Units: g

Gasoline Range Organics Soil Aliquot Vol: uL Test:

Extraction Type: Injection Volume:

PH: GPC Factor:

Prep Method:

File ID/Qc Batch: Dilution: Date Analyzed Prep Batch ID

FB031369.D 01/29/25 15:01 FB012925

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units(Dry Weight)
TARGETS GRO	GRO	53.0	U	9.00	53.0	ug/kg
SURROGATES 98-08-8	Alpha,Alpha,Alpha-Trifluorot	o 16.5		50 - 150	83%	SPK: 20

Comments:

U = Not Detected

LOO = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit