

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Date Received:

01/28/25

**SOIL** 

Fax: 908 789 8922

## **Report of Analysis**

Client: RU2 Engineering, LLC

U2 Engineering, LLC Date Collected: 01/27/25

Project: NYCDDC SANTWOBR Brooklyn Bridge BBMCR

Client Sample ID: JPP-16.3-012725 SDG No.: Q1206

Lab Sample ID: Q1206-05 Matrix:

Analytical Method: 8015D GRO % Solid: 85.9 Decanted:

Sample Wt/Vol: 5.09 Units: g Final Vol: 5 mL

Soil Aliquot Vol: uL Test: Gasoline Range Organics

Extraction Type: Injection Volume:

GPC Factor: PH:

Prep Method:

File ID/Qc Batch: Dilution: Date Analyzed Prep Batch ID

FB031370.D 1 01/29/25 15:28 FB012925

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units(Dry Weight)
TARGETS GRO	GRO	51.0	U	9.00	51.0	ug/kg
SURROGATES 98-08-8	Alpha,Alpha,Alpha-Trifluorot	o 12.8		50 - 150	64%	SPK: 20

## Comments:

U = Not Detected

LOO = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

\* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit