

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Date Received:

Matrix:

01/28/25

SOIL

mL

Fax: 908 789 8922

Report of Analysis

Client: RU2 Engineering, LLC

2 Engineering, LLC Date Collected: 01/27/25

Project: NYCDDC SANTWOBR Brooklyn Bridge BBMCR

JPP-20.2-012725MSD SDG No.: Q1207

Lab Sample ID: Q1207-17MSD

Analytical Method: 8015D GRO % Solid: 88.1 Decanted:

Sample Wt/Vol: 5.05 Units: g Final Vol: 5

Soil Aliquot Vol: uL Test: Gasoline Range Organics

Extraction Type: Injection Volume:

GPC Factor: PH:

Prep Method:

Client Sample ID:

File ID/Qc Batch: Dilution: Date Analyzed Prep Batch ID

FB031363.D 1 01/29/25 12:20 FB012925

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units(Dry Weight)
TARGETS GRO	GRO	185		9.00	51.0	ug/kg
SURROGATES 98-08-8	Alpha,Alpha,Alpha-Trifluoro	to 18.4		50 - 150	92%	SPK: 20

Comments:

U = Not Detected

LOO = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit