



Report of Analysis

Client: Weston Solutions Date Collected:

Project: Ft Meade Tipton Airfield Parcel RI - PO 0111169 Date Received:

Client Sample ID: VBF0129W1 SDG No.: Q1211
Lab Sample ID: VBF0129W1 Matrix: Water

Analytical Method: 8015D GRO % Solid: 0 Decanted:

Sample Wt/Vol: 5 Units: mL Final Vol: 5 mL

Soil Aliquot Vol: uL Test: Gasoline Range Organics

Extraction Type: Injection Volume:

GPC Factor: PH:

Prep Method:

File ID/Qc Batch: Dilution: Date Analyzed Prep Batch ID
FB031375.D 1 01/29/25 18:08 FB012925

Qualifier MDL LOD LOQ/CRQL Units **CAS Number Parameter** Conc. **TARGETS GRO GRO** 9.00 U 6.00 9.00 45.0 ug/L **SURROGATES** 98-08-8 Alpha, Alpha, Alpha-Trifluoroto 21.0 50 - 150 105% SPK: 20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit