

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Tully Environmental, Inc Date Collected: 01/28/25 13:00 Project: Transfer Station-SPDES Date Received: 01/29/25 Client Sample ID: 001-WILLETS-PT-BLVD(JAN) SDG No.: Q1212 Lab Sample ID: Q1212-01 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TSS	27.6	1 1.00	4.00	mg/L		01/30/25 09:15	5 SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits