

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	Q1212
Project:	Transfer Station-SPDES	Sample ID:	Q1212-01
Client ID:	001-WILLETS-PT-BLVD(JAN)DUP	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
TSS	mg/L	+/-5	27.6		28.0		1	1.44		01/30/2025