



Report of Analysis

Client: RU2 Engineering, LLC Date Collected:

Project: NYCDDC SANTWOBR Brooklyn Bridge BBMCR Date Received:

Client Sample ID: VBF0130S2 SDG No.: Q1215
Lab Sample ID: VBF0130S2 Matrix: SOIL

Analytical Method: 8015D GRO % Solid: 100 Decanted:

Sample Wt/Vol: 5 Units: g Final Vol: 5 mL

Soil Aliquot Vol: uL Test: Gasoline Range Organics

Extraction Type: Injection Volume :

GPC Factor: PH:

Prep Method:

File ID/Qc Batch: Dilution: Date Analyzed Prep Batch ID

FB031383.D 50 01/30/25 10:13 FB013025

| CAS Number | Parameter | Conc. | Qualifier | MDL | LOQ / CRQL | Units(Dry Weight) |
|-----------------------|------------------------------|---------|-----------|----------|------------|-------------------|
| TARGETS GRO | GRO | 2250 | U | 386 | 2250 | ug/kg |
| SURROGATES 98-08-8 | Alpha,Alpha,Alpha-Trifluorot | to 18.6 | | 50 - 150 | 93% | SPK: 20 |

Comments:

U = Not Detected

LOO = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit