

LAB CHRONICLE

OrderID:	Q1216	OrderDate:	1/29/2025 11:54:00 AM
Client:	RU2 Engineering, LLC	Project:	NYCDDC SANTWOBR Brooklyn Bridge BBMCR
Contact:	Rutu Manani	Location:	E11,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1216-03	JPP-18.1-012825	SOIL			01/28/25 08:41			01/29/25
			Paint Filter	9095B			01/31/25 11:08	
Q1216-04	JPP-18.1-012825	SOIL			01/28/25 08:41			01/29/25
			Corrosivity	9045D			01/30/25 14:33	
			Ignitability	1030			01/31/25 09:52	
			Reactive Cyanide	9012B		01/30/25	01/30/25 13:14	
			Reactive Sulfide	9034		01/30/25	01/30/25 15:42	
Q1216-07	JPP-21.1-012825	SOIL			01/28/25 09:30			01/29/25
			Paint Filter	9095B			01/31/25 11:15	
Q1216-08	JPP-21.1-012825	SOIL			01/28/25 09:30			01/29/25
			Corrosivity	9045D			01/30/25 14:37	
			Ignitability	1030			01/31/25 10:00	
			Reactive Cyanide	9012B		01/30/25	01/30/25 13:14	
			Reactive Sulfide	9034		01/30/25	01/30/25 15:45	

LAB CHRONICLE

Q1216-11	JPP-21.2-012825	SOIL		01/28/25 10:50		01/29/25
			Paint Filter	9095B		01/31/25 11:22
Q1216-12	JPP-21.2-012825	SOIL		01/28/25 10:50		01/29/25
			Corrosivity	9045D		01/30/25 14:40
			Ignitability	1030		01/31/25 10:08
			Reactive Cyanide	9012B	01/30/25	01/30/25 13:14
			Reactive Sulfide	9034	01/30/25	01/30/25 15:48
Q1216-15	JPP-26.1-012825	SOIL		01/28/25 11:35		01/29/25
			Paint Filter	9095B		01/31/25 11:30
Q1216-16	JPP-26.1-012825	SOIL		01/28/25 11:35		01/29/25
			Corrosivity	9045D		01/30/25 14:46
			Ignitability	1030		01/31/25 10:15
			Reactive Cyanide	9012B	01/30/25	01/30/25 13:14
			Reactive Sulfide	9034	01/30/25	01/30/25 15:52
Q1216-19	JPP-26.2-012825	SOIL		01/28/25 13:32		01/29/25
			Paint Filter	9095B		01/31/25 11:38
Q1216-20	JPP-26.2-012825	SOIL		01/28/25 13:32		01/29/25
			Corrosivity	9045D		01/30/25 14:50

LAB CHRONICLE

Ignitability	1030		01/31/25 10:22
Reactive Cyanide	9012B	01/30/25	01/30/25 13:14
Reactive Sulfide	9034	01/30/25	01/30/25 15:55