

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: RU2 Engineering, LLC

NYCDDC SANTWOBR Brooklyn Bridge BBMCR

Client Sample ID: JPP-21.2-012825

Lab Sample ID: Q1216-09

Analytical Method: 8015D GRO

Sample Wt/Vol: 5.09 Units: g

Soil Aliquot Vol: uL

Extraction Type:

GPC Factor: PH:

Prep Method:

Project:

File ID/Qc Batch: Dilution:

Date Analyzed 01/30/25 22:13

Date Collected:

Date Received:

SDG No.:

Matrix:

% Solid:

Final Vol:

Injection Volume:

Test:

01/28/25

01/29/25

Q1216

SOIL

84.3

5

Prep Batch ID

Decanted:

mL

FB031406.D 50

FB013025

Gasoline Range Organics

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units(Dry Weight)
TARGETS GRO	GRO	520	J	450	2620	ug/kg
SURROGATES 98-08-8	Alpha,Alpha,Alpha-Trifluorot	to 19.4		50 - 150	97%	SPK: 20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit