

Report of Analysis

Client:	RU2 Engineering, LLC		Date Col	lected: 01/29/2	5 12:30	
Project:	NYCDDC SANTWOBR Brooklyn Bridge BBMCR		Date Rec	eived: 01/30/2	5	
Client Sample ID:	JPP-42.2-012925	SDG No.	: Q1232			
Lab Sample ID:	Q1232-15		Matrix:	SOIL	SOIL	
			% Solid:	93.2		
Parameter	Conc. Qua. DF MDL	LOQ / CRQL	Units Prej	p Date Date Ana.	Ana Met.	
Paint Filter	1.00 U 1 1.00	1.00	ml/100gm	02/04/25 08:	55 9095B	

Comments:

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

- J = Estimated Value
- B = Analyte Found in Associated Method Blank
- * = indicates the duplicate analysis is not within control limits.
- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits