



Report of Analysis

Client: RU2 Engineering, LLC Date Collected:

Project: NYCDDC SANTWOBR Brooklyn Bridge BBMCR Date Received:

Client Sample ID: VBF0203S1 SDG No.: Q1232
Lab Sample ID: VBF0203S1 Matrix: SOIL

Analytical Method: 8015D GRO % Solid: 100 Decanted:

Sample Wt/Vol: 5 Units: g Final Vol: 5 mL

Soil Aliquot Vol: uL Test: Gasoline Range Organics

Extraction Type: Injection Volume:

GPC Factor: PH:

Alpha, Alpha, Alpha-Trifluoroto 18.5

Prep Method:

98-08-8

File ID/Qc Batch: Dilution: Date Analyzed Prep Batch ID

FB031440.D 1 02/03/25 11:47 FB020325

CAS Number Parameter Conc. Qualifier MDL LOQ / CRQL Units(Dry Weight)

TARGETS
GRO GRO 45.0 U 8.00 45.0 ug/kg

SURROGATES

50 - 150

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

92%

SPK: 20

() = Laboratory InHouse Limit