

Client Sample ID:

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

JPP-51.2-012925

Report of Analysis

Client: RU2 Engineering, LLC Date Collected: 01/29/25 15:00

Project: NYCDDC SANTWOBR Brooklyn Bridge BBMCR Date Received: 01/30/25

Lab Sample ID: Q1235-03 Matrix: SOIL

% Solid: 91.8

Q1235

SDG No.:

Parameter	Conc.	Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Paint Filter	1.00	U	1 1.00	1.00	ml/100gm		01/31/25 13:15	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits