



## **Report of Analysis**

Client: RU2 Engineering, LLC

Date Collected: 01/31/25

Project: NYCDDC SANTWOBR Brooklyn Bridge BBMCR

Date Received: 01/31/25

Client Sample ID: PIBLK-FE052179.D

SDG No.: Q1241

Lab Sample ID: I.BLK-FE052179.D

Matrix:

Water

Analytical Method:

8015D DRO

% Solid:

Decanted:

Sample Wt/Vol:

1000 Units: mL

Final Vol:

mL

Soil Aliquot Vol:

uL

Test:

Diesel Range Organics

Extraction Type:

Injection Volume:

GPC Factor :

PH:

Prep Method :
File ID/Qc Batch:

SW3510 Dilution:

Prep Date

Date Analyzed

Prep Batch ID

FE052179.D

1

01/31/25

FE013125

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units
TARGETS DRO	DRO	50.0	U	10.0	50.0	ug/L
<b>SURROGATES</b> 16416-32-3	Tetracosane-d50	16.3		29 - 130	82%	SPK: 20

## Comments:

U = Not Detected

LOO = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

\* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit