

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

% Solid:

91.2

Report of Analysis

Client: **PSEG** Date Collected: 02/03/25 10:15 Project: Trenton Gas and Appliance Service MA00006789 Date Received: 02/03/25 Client Sample ID: TR-05-020325 SDG No.: Q1276 Lab Sample ID: Q1276-01 Matrix: SOIL

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigl	nt) Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.085	U	1	0.085	0.43	mg/Kg	02/05/25 08:00	02/05/25 16:29	7196A
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		02/04/25 10:40	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits