

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 02/03/25 10:33 Project: Somerset HQ Date Received: 02/03/25 Client Sample ID: COMP-2 SDG No.: Q1279 Lab Sample ID: Q1279-02 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.20	Н	1	0	0	рН		02/04/25 16:35	9045D
Ignitability	NO		1	0	0	oC		02/05/25 11:00	1030
Reactive Cyanide	0.050	U	1	0.0087	0.050	mg/Kg	02/04/25 16:00	02/05/25 10:37	9012B
Reactive Sulfide	6.30	J	1	0.19	10.0	mg/Kg	02/04/25 12:05	02/04/25 16:35	9034

Comments: pH result reported at temperature 21.0 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits