

## Report of Analysis

|                    |                         |                 |              |
|--------------------|-------------------------|-----------------|--------------|
| Client:            | GFE LLC                 | Date Collected: | 02/05/25     |
| Project:           | 55 Contant Ave Lodi, NJ | Date Received:  | 02/05/25     |
| Client Sample ID:  | SV2                     | SDG No.:        | Q1302        |
| Lab Sample ID:     | Q1302-02                | Matrix:         | Air          |
| Analytical Method: | TO-15                   | Test:           | VOCMS Group3 |
| Sample Wt/Vol:     | 400      Units:    mL   |                 |              |

|                   |           |           |                |               |
|-------------------|-----------|-----------|----------------|---------------|
| File ID/Qc Batch: | Dilution: | Prep Date | Date Analyzed  | Prep Batch ID |
| VL041983.D        | 4         |           | 02/10/25 12:35 | VL021025      |

| CAS Number                | Parameter               | Conc.<br>ppbv | Conc.<br>ug/M3 | Qualifier | MDL      | LOQ / CRQL | Units   |
|---------------------------|-------------------------|---------------|----------------|-----------|----------|------------|---------|
| <b>TARGETS</b>            |                         |               |                |           |          |            |         |
| 75-01-4                   | Vinyl Chloride          | 0.060         | 0.15           | U         | 0.15     | 0.31       | ug/m3   |
| 75-35-4                   | 1,1-Dichloroethene      | 0.56          | 2.22           | U         | 2.22     | 7.93       | ug/m3   |
| 156-59-2                  | cis-1,2-Dichloroethene  | 0.36          | 1.43           | U         | 1.43     | 7.93       | ug/m3   |
| 71-55-6                   | 1,1,1-Trichloroethane   | 0.78          | 4.26           |           | 0.22     | 0.65       | ug/m3   |
| 79-01-6                   | Trichloroethene         | 0.070         | 0.38           | U         | 0.38     | 0.64       | ug/m3   |
| 127-18-4                  | Tetrachloroethene       | 1.20          | 8.14           |           | 0.41     | 0.81       | ug/m3   |
| <b>SURROGATES</b>         |                         |               |                |           |          |            |         |
| 460-00-4                  | 1-Bromo-4-Fluorobenzene | 9.40          |                |           | 65 - 135 | 94%        | SPK: 10 |
| <b>INTERNAL STANDARDS</b> |                         |               |                |           |          |            |         |
| 74-97-5                   | Bromochloromethane      | 157000        |                |           | 2.784    |            |         |
| 540-36-3                  | 1,4-Difluorobenzene     | 438000        |                |           | 3.956    |            |         |
| 3114-55-4                 | Chlorobenzene-d5        | 397000        |                |           | 8.875    |            |         |

U = Not Detected

RL = Reporting Limit

MDL = Method Detection Limit

E = Value Exceeds Calibration Range

D = Dilution

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

\* = Values outside of QC limits

Q = indicates LCS control criteria did not meet requirements