

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Date Collected:

Date Received:

SDG No.:

Matrix:

% Solid:

Final Vol:

Injection Volume:

Test:

02/07/25

Fax: 908 789 8922

Report of Analysis

Client: ENTACT

North Point - 4101 Arthur Kill Rd - E9306

Client Sample ID: PIBLK-FG015345.D

Lab Sample ID: I.BLK-FG015345.D

Analytical Method: 8015D DRO

Sample Wt/Vol: 1000 Units: mL

Soil Aliquot Vol: uL

Extraction Type:

FG015345.D

Project:

GPC Factor: PH:

Prep Method: SW3510

File ID/Qc Batch: Dilution:

Prep Date

Date Analyzed Prep Batch ID

02/07/25

02/07/25

Q1308

Water

FG020725

Diesel Range Organics

Decanted:

mL

Qualifier MDL LOQ / CRQL Units **CAS Number Parameter** Conc. **TARGETS** DRO DRO 10.0 U 10.0 50.0 ug/L **SURROGATES** 16416-32-3 Tetracosane-d50 18.3 29 - 130 92% SPK: 20

Comments:

U = Not Detected

LOO = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit