

## Report of Analysis

Client:	VERINA CONSULTING GROUP, LLC	Date Collected:	02/06/25 13:20
Project:	Rotor Clip NJ WTD - 2025	Date Received:	02/06/25
Client Sample ID:	WATER TREATMENT DISCHARGE	SDG No.:	Q1324
Lab Sample ID:	Q1324-01	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ammonia as N	2.10	OR	1	0.045	0.10	mg/L	02/07/25 09:10	02/07/25 12:33	SM 4500-NH3 B plus G-11
Residual Chlorine	1.12	H	1	0.016	0.10	mg/L		02/07/25 10:42	SM 4500-Cl G-11

Comments: \_\_\_\_\_

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits