

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: VERINA CONSULTING GROUP, LLC Date Collected: 02/06/25 13:20

Project: Rotor Clip NJ WTD - 2025 Date Received: 02/06/25

Client Sample ID: WATER TREATMENT DISCHARGEDL SDG No.: Q1324

Lab Sample ID: Q1324-01DL Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ammonia as N	2.40	D	2	0.090	0.20	mg/L	02/07/25 09:10	02/07/25 13:34	SM 4500-NH3
									B plus G-11

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits