

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 02/10/25 13:57 Project: Camden Gas M&R Project Date Received: 02/10/25 Client Sample ID: SOIL-COMP SDG No.: Q1346 Lab Sample ID: Q1346-01 Matrix: SOIL % Solid: 86.8

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	nt) Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.72		1	0.089	0.45	mg/Kg	02/12/25 10:00	02/12/25 15:09	7196A
Ignitability	NO		1	0	0	oC		02/11/25 10:52	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		02/13/25 08:25	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits