

Report of Analysis

Client:	Weston Solutions	Date Collected:	02/10/25 13:40
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169	Date Received:	02/11/25
Client Sample ID:	TAP-IDW-SOIL-021025	SDG No.:	Q1352
Lab Sample ID:	Q1352-01	Matrix:	SOIL
		% Solid:	74.7

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.25	U	1	0.056	0.25	0.32	mg/Kg	02/11/25 14:40	02/11/25 16:51	9012B
Ignitability	NO		1	0	0	0	oC		02/12/25 10:15	1030
pH	10.1	H	1	0	0	0	pH		02/12/25 08:45	9045D
Sulfide	4.27	J	1	2.48	6.67	13.3	mg/Kg	02/12/25 09:10	02/12/25 12:36	9034

Comments: pH result reported at temperature 20.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits