

Report of Analysis

Client:	Parkway Generation Operating LLC	Date Collected:	02/11/25 12:14
Project:	Linden Generating Station - 402	Date Received:	02/11/25
Client Sample ID:	CARBON-SOLID	SDG No.:	Q1356
Lab Sample ID:	Q1356-01	Matrix:	SOIL
		% Solid:	44.5

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.24	H	1	0	0	pH		02/12/25 13:30	9045D
Ignitability	NO		1	0	0	oC		02/12/25 10:37	1030
Reactive Cyanide	0.014	J	1	0.0087	0.050	mg/Kg	02/13/25 09:00	02/13/25 11:29	9012B
Reactive Sulfide	4.76	J	1	0.19	10.0	mg/Kg	02/12/25 11:10	02/12/25 13:57	9034
TPH	135		1	14.0	56.2	mg/Kg		02/14/25 09:38	9071B

Comments: pH result reported at temperature 20.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits