

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q1356

Project: 323562

RunNo.: LB134676

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV pH	pH	6.98	7	100	90-110	02/12/2025
Sample ID: CCV1 pH	pH	2.02	2.00	101	90-110	02/12/2025
Sample ID: CCV2 pH	pH	12.02	12.00	100	90-110	02/12/2025

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q1356

Project: 323562

RunNo.: LB134690

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
Corrosivity		pH	7.02	7	100	90-110	02/12/2025
Sample ID:	CCV1						
Corrosivity		pH	2.01	2.00	101	90-110	02/12/2025
Sample ID:	CCV2						
Corrosivity		pH	12.02	12.00	100	90-110	02/12/2025

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q1356

Project: 323562

RunNo.: LB134703

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.096	0.099	97	85-115	02/13/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	02/13/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	02/13/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	02/13/2025

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q1356

Project: 323562

RunNo.: LB134707

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV						
Flash Point	o F	82.7	81	102	78-84	02/13/2025

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q1356

Project: 323562

RunNo.: LB134707

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
---------	-------	--------	------------	---------------	---------------------------	------------------