

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 02/14/25 10:21

Project: Audubon Gas and Appliance Service MA00006789 Date Received: 02/14/25

 Client Sample ID:
 AU-05-021425
 SDG No.:
 Q1372

 Lab Sample ID:
 Q1372-01
 Matrix:
 SOIL

% Solid: 100

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
pН	7.85 H	1 0	0	pН		02/17/25 09:10	9045D

Comments: pH result reported at temperature 22.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits