



LAB CHRONICLE

OrderID: Q1382	OrderDate: 2/18/2025 10:57:00 AM
Client: Nobis Group	Project: Raymark Superfund Site
Contact: Adam Roy	Location: H31,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1382-01	OU4-PCS-TC-01-0217 25	SOIL			02/17/25 08:30			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:27	
Q1382-03	OU4-PCS-TC-02-0217 25	SOIL			02/17/25 08:35			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:27	
Q1382-05	OU4-PCS-TC-03-0217 25	SOIL			02/17/25 08:40			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:34	
Q1382-07	OU4-PCS-TC-04-0217 25	SOIL			02/17/25 08:45			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:34	
Q1382-09	OU4-PCS-TC-05-0217 25	SOIL			02/17/25 08:50			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:34	
Q1382-11	OU4-PCS-TC-06-0217 25	SOIL			02/17/25 08:55			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:34	
Q1382-13	OU4-PCS-TC-07-0217 25	SOIL			02/17/25 09:00			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:34	

LAB CHRONICLE

Q1382-15	OU4-PCS-TC-08-0217 25	SOIL			02/17/25 09:05			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:34	
Q1382-17	OU4-PCS-TC-09-0217 25	SOIL			02/17/25 09:10			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:34	
Q1382-19	OU4-PCS-TC-10-0217 25	SOIL			02/17/25 09:15			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:34	
