

LAB CHRONICLE

OrderID:	Q1383	OrderDate:	2/18/2025 11:19:00 AM
Client:	Nobis Group	Project:	Raymark Superfund Site
Contact:	Adam Roy	Location:	H31,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q1383-01	OU4-PCS-TC-11-0217 25	SOIL	Cyanide	9012B	02/17/25 09:20	02/19/25	02/19/25 13:42	02/18/25
Q1383-03	OU4-PCS-TC-12-0217 25	SOIL	Cyanide	9012B	02/17/25 09:25	02/19/25	02/19/25 13:42	02/18/25
Q1383-05	OU4-PCS-TC-13-0217 25	SOIL	Cyanide	9012B	02/17/25 09:30	02/19/25	02/19/25 13:42	02/18/25
Q1383-07	OU4-PCS-TC-14-0217 25	SOIL	Cyanide	9012B	02/17/25 09:35	02/19/25	02/19/25 13:49	02/18/25
Q1383-09	OU4-PCS-TC-15-0217 25	SOIL	Cyanide	9012B	02/17/25 09:40	02/19/25	02/19/25 13:49	02/18/25
Q1383-11	OU4-PCS-TC-16-0217 25	SOIL	Cyanide	9012B	02/17/25 09:45	02/19/25	02/19/25 13:49	02/18/25
Q1383-13	OU4-PCS-TC-17-0217 25	SOIL	Cyanide	9012B	02/17/25 09:50	02/19/25	02/19/25 13:49	02/18/25

LAB CHRONICLE

Q1383-15	OU4-PCS-TC-18-0217 25	SOIL			02/17/25 09:55			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:49	
Q1383-17	OU4-PCS-TC-19-0217 25	SOIL			02/17/25 10:00			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:49	
Q1383-19	OU4-PCS-TC-20-0217 25	SOIL			02/17/25 10:05			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:55	
Q1383-21	OU4-CF-15-021725	SOIL			02/17/25 08:15			02/18/25
			Cyanide	9012B		02/19/25	02/19/25 13:49	
